

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11025

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080008-5

RECEIVED FROM

DATE REC'D

3-24-57

P.O. NO.

VENDOR PACKING SLIP NO.

O ACCT. OR
R W.O. NO.

S.O. NO.

REMARKS

CHARGE TO
QUANTITY
RECEIVEDCONTRACT
CODE NO.

322DRAWING
NUMBER

000000DWG. DASH OR
STANDARD PART NO.

12140DWG.
REV.

0LOT
NO.

0CLASS
NUMBER

03OPR.
NUMBER

00BUY OUT
CODE NO.

OACCT. OR
R W.O. NO.

S.O. NO.

QUANTITY
ACCEPTED
REJECTED

12

731258-1 "D" ROCKER BRAKE

12

SHIPPER 85652

TO SURVEYOR 128151

*J. F. Kanda*RECEIVED
BYINSPECTED
BY

Date 1/25/57

REJECTS RETURNED
ON SHIP. MEMO NO.

HMC-1069

RECEIVED FROM

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11026

DATE REC'D

3-23-57

P.O. NO.

VENDOR PACKING SLIP NO.

O ACCT. OR
R W.O. NO.

S.O. NO.

REMARKS

CHARGE TO
QUANTITY
RECEIVEDCONTRACT
CODE NO.

322DRAWING
NUMBER

000000DWG. DASH OR
STANDARD PART NO.

12140DWG.
REV.

0LOT
NO.

0CLASS
NUMBER

03OPR.
NUMBER

00BUY OUT
CODE NO.

OACCT. OR
R W.O. NO.

S.O. NO.

QUANTITY
ACCEPTED
REJECTED

12

731258-2 "D" ROCKER BRAKE

12

SHIPPER 85652

TO SURVEYOR 128152

J. F. Kanda

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080008-5

RECEIVED
BYINSPECTED
BY

Date 1/25/57

REJECTS RETURNED